

Corn Exchange

Opportunity	Action completed	Action in progress	Not begun but intending to	Not begun, not intending to	Not applicable
1) Manage heating	☒	☐	☐	☐	☐
2) Conduct an out of hours survey	☐	☒	☐	☐	☐
3) Upgrade lighting to LEDs	☐	☒	☐	☐	☐
4) Add draught proofing to external doors	☐	☐	☒	☐	☐
5) Install secondary glazing	☐	☐	☐	☒	☐
6) Manage summer heat	☐	☐	☒	☐	☐
7) Add solar PV panels	☐	☒	☐	☐	☐
8) Consider an air to water heat pump system	☐	☒	☐	☐	☐

Windrush Cemetery

Opportunity	Action completed	Action in progress	Not begun but intending to	Not begun, not intending to	Not applicable
1) Take & submit meter readings	☐	☐	☒	☐	☐
2) Add heating controls* (<i>depends on 10</i>)	☐	☐	☐	☒	☐
3) Add loft insulation	☐	☒	☐	☐	☐
4) Add timer to hot water	☐	☒	☐	☐	☐
5) Upgrade lighting to LEDs	☐	☒	☐	☐	☐
6) Add draught proofing to external door	☐	☒	☐	☐	☐
7) Investigate fridge use	☐	☐	☐	☒	☐
8) Provide signage for disabled toilet door	☐	☒	☐	☐	☐
9) Add solar PV panels	☐	☒	☐	☐	☐
10) Consider an air-to-air heat pump	☐	☒	☐	☐	☐

Burwell Hall

Opportunity	Action completed	Action in progress	Not begun but intending to	Not begun, not intending to	Not applicable
1) Option A – Ground Source Heat Pump*	☐	☐	☐	☐	☒
2) Option B – Air source heat pump (air to air)*	☐	☐	☐	☐	☒
3) Timers for hot water heaters	☐	☐	☒	☐	☐
4) Zone heating in the changing rooms	☐	☐	☒	☐	☐
5) Replace lights with LEDs	☐	☒	☐	☐	☐
6) Solar PV panels	☐	☐	☒	☐	☐
7) Ceiling insulation	☐	☐	☒	☐	☐
8) Additional low & no cost measures	☐	☐	☐	☐	☐
a) Repair the thermostat/check the programmer	☐	☐	☐	☐	☒
b) Set heating time to match usage	☒	☐	☐	☐	☐
c) Make use of the ventilation system in the main hall	☐	☐	☒	☐	☐
d) Turn off the kitchen hot water boiler when not in use	☐	☐	☒	☐	☐
e) Take and report gas meter readings	☒	☐	☐	☐	☐

*Survey taken in 2022. Replacement energy efficient gas boiler was installed.