

High Street

Reference	Location	Item	Conditon
BS 1	Opposite side to Town Hall	Bus shelter with bench	Good need a clean
BS2	Opposite side to Town Hall	Bus shelter with bench	Good need a clean
BS3	Outside Lilly's attic	Bus shelter	Good needs a clean
BS4	Outside Densham's/Niche	Bus shelter	Ok needs a clean
BH1	Outside HSBC	Bench	Good
BH2	Outside Beekeepers	Bench	Ok could do with a restrain
BH3	Outside Part & Parcel	Bench	Good
BH4	Outside Halifax	Bench	Ok but needs a restrain *chat bench*
	Facing Corn Exchange on Market		
BH5	Square	Bench	Ok but needs a restrain
BH6	Facing road Market Sqaure	Bench	Ok but needs a restrain
BH7	Outside Town Hall	Bench	Ok but needs a restrain
BH8	Outside Town Hall	Bench	Ok but needs a restrain
CR1	Rear of Town Hall by DSO office	Cycle racks	Good
CR2	By post Box at Part and Parcel	Cycle racks	Good
CR3	Outside Lloyds Bank/ Toy Galaxy	Cycle racks	Good
CR4	Outside Niche	Cycle racks	Good
CR5	Outside Halifax	Cycle racks	Good
CR6	Adjacent to Robert Dyas	Cycle racks	Good
PL1	Corner outside Natwest	3 Metal planters	Good
PL2	Corner outside Halifax	3 Metal planters	Good
DF1	In telephone box	Defibrillator	Good
NB1	Town Hall front	Town Council notice board	Good
NB2	At side of Town Hall	Town Notice board	Good
CR7	Outside R.N Peace	Cycle racks	Good
CR8	Opposite Mahams	Cycle racks	Good
BH9	Next to Smart's	Bench	Fair
NB3	Front of Corn Exchange	Notice Board/Menu cabinet	Good
NB4	Front of Corn Exchange	Notice Board	Good

The Leys

Reference	Location	Item	Conditon
PL1	Just past entrance from Church	Planter	Ok but needs graffiti removing and a replacement sticker
BN1	1st Bench along top road	Bench	Sound - needs a sand and stain
CR1	along top road	Cycle racks root fix	Good
BI1	along top road	Double bin	Good but needs graffiti removal
BN2	along top road	Bench	Ok but needs a sand and stain
BN3	along top road	Eastgate bench	ok but top slat is bowed and needs cleaning, sanding and staining
HO	along top road	Hang Out Shelter	Good
BI2	along top road	Double bin	Good but needs a clean and replacement sticker
PL2	along top road	White planter	Good
BN4	along top road	Eastgate bench	Good but needs a clean, sand and stain
PL3	along top road	White planter	Good
BI3	along top road	Double bin	Good but needs a clean and replacement sticker
BN5	along top road	Bench	Ok but needs a sand and stain
PL4	along top road	White stone planter	Needs repainting and some decent plants
PL5	along top road	White stone planter	Needs repainting and some decent plants
B14	along top road	Double bin	Ok but needs graffiti removal and a replacement sticker
BN6	along top road	Eastgate bench	ok, needs a clean
BI5	along top road in the car park at junction of top road and depot road	Double bin	Ok, needs a clean and replacement sticker
CR2	at junction of top road and depot road	Ground fix green cycle racks	Good.
BN7	at junction of top road and depot road	Memorial bench	Needs a sand and stain. Memorial plaque gone.

			Good condition. Needs Continental sticker removing end of Septembert
PL6	along depot road	Planter	Needs a sand and stain. Memorial plaque gone.
BN8	along depot road	Memorial bench	Needs cleaning and replacement sticker
PL7	along depot road	Planter	Needs cleaning and replacement sticker
PL8	along depot road	Planter	Needs a sand and stain. Memorial plaque gone.
BN9	along depot road	Memorial bench	Good
WM	corner by coffeeshed	War memorial	Needs a clean and new sticker
PL9	In front of skatepark	Planter	Good
BN10	In front of skatepark	Eastgate bench	Good
TB1	In front of skatepark	TeqballTable	Needs a clean
PL10	In front of skatepark	Planter	Needs a stain
BN11	In front of skatepark	Memorial bench	Good
PL11	In front of mini golf	Planter	Good - possibly needs a clean
BI6	In front of mini golf	Double bin	Needs repainting
BN12	In front of mini golf	Metal Picnic bench	Good
BN13	Just past mini golf	Eastgate bench	Good - possibly needs a clean
PL12	Just past mini golf	Planter	Good
BN14	Just before entrance to play area	Eastgate bench	Good
NB1	Just before entrance to play area	Noticeboard	Good
CR3	Outside play area	Green ground fix cycle racks	Good
PL13	Just after play area entrance	Planter	Good - possibly needs a clean
BI7	At Sainsbury's Corner entrance	Double bin	Good
	At bottom end of main path through trees		
BI8		Double bin	Good
BI9	On path through main trees	Double bin	Good
	Main path through trees on events field side		
BN15		Eastgate bench	Good
BN16	Main path cricket side	Eastgate bench	Good
CR4	Main path cricket side	Ground fix metal cycle racks	Good
	Just by pillar at Church path entrance		
PL14		Planter	Needs pumpkin graffiti removed

Welch Way

Reference	Location	Item	Conditon
PN 1 - 3	Outside College 2 same side one other side	Planters	Good
PN 4-5	Outside library and opposite library	Planters	Good
PN6 - 8	Outside and opposite Rowlands Pharmacy	Planters	Good
PN9	Outside Card Factory	Planter	Good
PN10	Outside Town Centre Shop	Planter	Good
BN1	Outside College	Bench	Good - Needs a restrain
BN2	Outside College	Bench	Good - Needs a restrain
BN3	Outside library	Bench	Older style - stucture is ok but very tatty.Needs a restrain
BN4 and 5	Outside library	Bench	Ok -Needs a restrain
BN6 and 7	Outside Nuffield Health centre	Bench	Good
BN8	Corner of slip road to Welch Way Bungalows	Bench	Poor - needs renewing
CR1 - 7	Outside library	Cycle racks - ground fix	Good
CR8 - 17	To left of bus shelter, Café Nero	Cycle racks - ground fix	Good
CR18 - 23	To right of bus shelter, entrance to Marriots Walk	Cycle racks - ground fix	Good
CR24 - 29	Outside Nuffied Health Centre, near corner (road to rear Co Op)	Cycle racks - ground fix	Good Ok but looks as though there is rust on at least one bottom panel. Perspex needs cleaning up.
BS1	Outside café Nero	Bus shelter	up.
PN11	Outside Natwest	Brick built flower bed	Good

Langdale Gate

Reference	Location	Item	Conditon
FB1	By roadside adjacent to Waite's Deli car park	Brick flower bed	Fair
MB1	By Langdale Hall Car Park	Memorial Bench (Booth and Simms)	Needs rub down and restrain

Raleigh Crescent

Reference	Location	Item	Conditon
-----------	----------	------	----------

BS1	near Bourton Close	Bus shelter no seat	Perpex needs cleaning otherwise good.
-----	--------------------	---------------------	---

Valence Crescent

Reference	Location	Item	Conditon
BS1	Near Broadway Close	Bus shelter no seat	Good

Burford Road

Reference	Location	Item	Conditon
BH1	Corner of Burford Road/Tower Hill Opposite Windrush	Eastgate Bench	Slats bowed, wood needs renovating and slat replacing.
BS1	Valley Road	Bus shelter	Ok - perspex dirty

Abbey Road

Reference	Location	Item	Conditon
-----------	----------	------	----------

BS1	Abbey Road Corner	Bus shelter no seat	Good - need stickers removing from perspex
-----	-------------------	---------------------	---

Cogges Hill Road

Reference	Location	Item	Conditon
CR1	On verge outside shops	Cycle racks	Good
NB1	On verge outside shops	Notice Board	Poor. Does not lock and when you lift to open the inner board falls out towards you - needs replacing or repair of some type.

Blakes Avenue

Reference	Location	Item	Conditon
-----------	----------	------	----------

BH1	Opposite no 46	Bench	Good, but bird fouling on it - may just need a clean
-----	----------------	-------	---

Oxford Hill

Reference	Location	Item	Conditon
BH1	Opposite 20 Oxford Hill	Bench	Poor - metal leg bent and wood is rough - ideally replace
BS1	Opposite 59 Oxford Hill	Bus shelter	Perspex vandalised and needs cleaning
CR1	Cycle racks 4 root fix	Cycle racks	Good

Woodstock Road

Reference	Location	Item	Conditon
WRBH1	Woodstock Road	Bench	Poor - needs replacing

Farmers Close

Reference	Location	Item	Conditon
-----------	----------	------	----------

BH1	Farmers Close Green rear of Woodgreen	Eastgate Bench	Ok but ideally rub down and restrain
-----	--	----------------	---

Madley Park

Reference	Location	Item	Conditon
BS1	On Madley Park side of A4095	Bus shelter	Tatty - perspex needs cleaning up
BS2	Opposite Madley Park A4095	Bus shelter	Tatty - perspex needs cleaning up

Newland & King George V Field

Reference	Location	Item	Conditon
BS1	Outside Cricket Club	Bus shelter	Tatty and missing a perspex panel
CR1	Outside Cricket Club	Cycle racks - root fix	Good
BN1	Near Kingsfield Crescent	Double bin	Good
BN2	By the MUGA	Double bin	Good
DB1	Adjacent to Pensclose	Dog bin	Good
DB2	By entrance	Dog Bin	Solid but bit tatty
BH1	By Play area	Eastgate Bench Eatsgate Memorial Bench	Ok, could do with a varnish
BH2	By Play area	Tobias Marnier	Ok, could do with a varnish

Witney Lake & Park

Reference	Location	Item	Conditon
DFB1	Entrance after underpass	Defibrillator	Excellent
DB1	Just before entrance gate	Dog bin	Fair
BI1	Just after entrance gate	Double bin	Good
NB1	Just the other side of entrance fence	Main sign board	Good
NB2	Right hand side just after entrance	Pictoral Main sign map board	Good
NB3	Just inside	Old wooden sign "Witney Lake"	Old but in keeping with natural look
CR1	Left hand side	Cycle racks ground fix	Good
NB4	see map	Bird notice board	Good but graffiti needs removing
PN 1 and 2	see map	Picnic benches - green metal	Good
BI2	see map	Double bin	Good
LB1	see map	Life buoy	Good
DB2	see map	Dog bin	Good
PN3	see map	Green metal pic nic bench	Good
FP1	see map	Fishing platform	Good
			Needs rubbing down and staining.
MB1	see map	Memorial Bench Wooden	Green
NB5	see map	Small fishing notice board	Good
	see map, just before Ducklington bridge		
BI3	entrance on right	Litter and recycling bin	Good
BN1	Opposite Duckington entrance	Metal black bench	Good
	see map, just before Ducklington bridge		
DB3	entrance on right	Dog bin	Good
LB2	see map	Life buoy attached to metal on bridge	Fair
NB6	see map - opposite Duckington bridge	Notice board - main	Good
BN2	see map	Wood bench with metal frame	Fair - structure ok
PC1	see map	Wood perch bench	fair
PC2	see map	Wood perch bench	Fair
NB7	see map, by meadow bridge	Main sign board	Good
PC3	see map	Wood perch bench	Fair

LB3	On meadow bridge	Life Buoy	Excellent
DB3	On meadow bridge	Dog bin	Excellent
BI4	see map	Double bin	Good
			Fair - structure ok, needs a rub down and revarnish/stain
MB2	see map	Wooden memorial bench	
BN3	see map	Wood and metal bench	Poor
PC4	see map	Wood perch bench	Fair
PC5	see map	Wood perch bench	Fair
LB4	see map	Life buoy	Poor - rusted into a hole at base
DB5	see map	Dog bin	Good
BN4	see map	Wooden bench with metal frame	Fair
BN5	see map	Wooden bench with metal frame	Good
PN4	see map	Metal picnic bench	Good
PN5	see map	Metal picnic bench	Good
PC5	see map	Wood perch bench	Fair
FP2	see map	Fishing platform	Very good
BN 6 and 7	at entrance/exit	Plastic benches	Good - need a clean

Church Green

Reference	Location	Item	Conditon
BN1	Church End of Green	Wooden bench	Ok
BN2	Church End of Green	Eastgate Bench	Good
BN3	T and C kitchen end of green	Eastgate Bench	Could do with a varnish
CR1	T and C kitchen end of green	Ground fix cycle racks	Good
BN4	T and C kitchen end of green	Bench	Needs a rub down and varnish
BN5	Side path T and C kitchen end of green	Memorial Eastgate Bench	Some bowing to wood, needs a rubdown and revarnish
BN6	Side path	Bench	Ok, could do with a revarnish
BN7	Side path	Bench	Ok, could do with a revarnish

Burwell Drive

Reference	Location	Item	Conditon
-----------	----------	------	----------

BS1	Outside Burwell Shops	Sedum roof bus shelter	Vandalised with graffiti. Needs removing. Also sedum roof may be dead through lack of watering during the very hot weather and not having an annual feed.
-----	-----------------------	------------------------	---

Sports Ground		West Witney Sports Ground	
Reference	Location	Item	Conditon
DB1	By entrance	Dog Bin	Very poor - needs replacing
B1	On building	Litter bin	Good
	Entrance to Deer Park		
B2	Wood	Litter bin	Good
	Entrance on right hand		
MR1	side	Memorial Airfield Rock	Excellent
	On clubhouse building by		
DF1	fire escape.	Defibrillator	Good

Burwell Recreation Ground

Reference	Location	Item	Conditon
SB1	To right of hall by path	Sign Board	Good
BN1	Adjacent to play area	Double bin	Good
PN1	Between hall and play area	Metal picnic bench	Good
PN2	Between hall and play area	Metal picnic bench	Good
DB1	At bottom end of playing field	Dog Bin	Poor - needs reattaching to post Structurally fine but wood needs rubbing down and restaining
MB1	At far end of football field At footpath to Burwell Meadow on football field	Memorial Bench (Warren)	
DB2		Dog bin	Good Structurally fine but wood needs rubbing down and restaining
MB2	By hedge between football and playing field	Memorial bench (Wilton)	Structurally fine but wood needs rubbing down and restaining
B1	By hedge between football and playing field On football side of hedge but adajacent to MUGA	Eastgate Bench	Structurally fine but wood needs rubbing down and restaining
BN2			
DF1	On Burwell Hall	Defibrillator	Good
NB1	On Burwell Hall	Notice Board	Reasonable

Curbridge Road

Reference	Location	Item	Conditon
BS1	Thorney Leys Roundabout end	Bus shelter	Perepex needs cleaning
CR1	Thorney Leys Roundabout end next to bus shelter	Cycle racks - 3 ground fixed	Good condition

Woodgreen & Little Green

Reference	Location	Item	Conditon
BLLD 1	Little Green	Bollards (wooden x 5)	Good condition
BH1	Woodgreen - top road	Bench	Eastgate - could do with rub down and restrain
BH2	Woodgreen - top road	Memorial Bench Bill and Elsie Barker	Eastgate - could do with rub down and restrain
BH3	Woodgreen - corner near Elmfield	Memorial Bench - Talking News	Eastgate - could do with rub down and restrain
BH4	Woodgreen Three pidgeons side	Bench	Could do with a rub down and re stain - looks ok structurally
BH5	Outside Play area	Bench	Eastgate - could do with rub down and restrain

Corn Street

Reference	Location	Item	Conditon
CR1	Outside the Three Horsehoes	Cycle racks (3 groundfix)	Good
BS1	Adjacent to 178 Corn Street	Bus shelter	Good
BS2	Opposite bus garage	Bus shelter	good

Witan Way

Reference	Location	Item	Conditon
BH1	Woodland Path (Leisure Centre end)	Wood and metal bench	Poor - ideally replace
BH2	Woodland path (Farm Mill end)	Wood and metal bench	Poor - ideally replace